# UNIVERSAL CABLETETHER ®

Be a
## Tech Hero.

Trusted by thousands of companies & government agencies around the world. Our product is proudly made with quality U.S. sourced parts and assembled by a U.S. military veteran.

Protect your gear, save the organization money & be the tech hero!

# INSTRUCTIONS

1. Insert the looped end over the display adapter *or* peripheral.

2. Insert the other looped end over the display cable *or* peripheral.

3. Tighten both loop ends to ensure they are secure to the cable.

4. Crimp the sleeve with a pair of standard pliers *or* electrical piers from the top/flat part of the sleeve. Squeeze securely in multiple different locations on the sleeve to ensure a solid hold (*recommend 4x evenly placed with medium pressure*). Repeat this process on the other side of cable.

5. You are now tethered!

*Thank you*
for purchasing the

# UNIVERSAL CABLETETHER ®