UNIVERSAL CABLETETHER ®

Be a
Tech Hero.

Trusted by thousands of companies & government agencies around the world. Our product is proudly made with quality U.S. sourced parts and assembled by a U.S. military veteran.

Protect your gear, save the organization money & be the tech hero!

INSTRUCTIONS

1. Loosen grub screws in clamp to ensure wire feeds in easily. They do not need to be completed removed.

2. Create a large loop at each end allowing the wire to feed into the clamp easily.

3. Position and tighten the loop around the peripherals at both ends.

4. Using the provided Allen wrench, tighten the grub screws on both ends

5. You are now tethered!

Thank you
for purchasing the

UNIVERSAL CABLETETHER ®